

## Fairford River Water Control Structure

Date	Bay											Total Logs in Place
	1	2	3	4	5	6	7	8	FISH LADDER 9	10	11	
2014-01-01	3	0	0	0	1	1	0	1		1	0	7
2014-11-06	+5	+4	+2	+5				+6		+8	+6	+36
	8	4	2	5	1	1	0	7		9	6	43
2014-11-07	+3					+2					+3	+8
	11	4	2	5	1	3	0	7		9	9	51
2015-03-06				+5			+1	+2				+8
	11	4	2	10	1	3	1	9		9	9	59
2015-03-11						+2						+2
	11	4	2	10	1	5	1	9		9	9	61
2015-04-14	-8			-7		-1		-3		-5	-7	-31
	3	4	2	3	1	4	1	6		4	2	30
2015-04-15	-3	-4		-2	-1	-4	-1	-4		-4	-1	-24
	0	0	2	1	0	0	0	2		0	1	6
2015-10-20	+4	+2		+1	+2	+1	+2			+2	+3	+17
	4	2	2	2	2	1	2	2		2	4	23
2015-11-06		+1	+1	+1	+1	+1	+1	+1		+1		+8
	4	3	3	3	3	2	3	3		3	4	31
2016-11-03				-3	-3	-2	-3			-3	-4	-18
	4	3	3	0	0	0	0	3		0	0	13
2016-11-07	-4	-3	-3					-3				-13
	0	0	0	0	0	0	0	0		0	0	0
2017-09-25				+5	+5	+5	+5	+5		+6	+6	+37
	0	0	0	5	5	5	5	5		6	6	37
2017-09-26				+3	+3	+3	+4	+5		+4	+3	+25
	0	0	0	8	8	8	9	10		10	9	62
2019-09-27				+1	+2	+1	+1					+5
	0	0	0	9	10	9	10	10		10	9	67
2017-09-28	+4	+8	+3							-10	-9	-4
	4	8	3	9	10	9	10	10		0	0	63
2017-09-29	+5	+2		-3	-3	-3	-3	-3				-8
	9	10	3	6	7	6	7	7		0	0	55
2017-09-30				-3	-3	-3	-3	-3				-15
	9	10	3	3	4	3	4	4		0	0	40
2017-10-02	-4	-5		-2	-2	-2	-2	-2				-19
	5	5	3	1	2	1	2	2		0	0	21
2017-10-03	-5	-5	-2	-1	-2	-1	-2	-2				-20
	0	0	1	0	0	0	0	0		0	0	1