



**Photograph 01. Maw Lake viewed from the south (5 Sept 2007)**



**Photograph 02. Wetland drainage from Maw Lake to Varnson Lake looking north (5 Sept 2007)**



**Photograph 03. Varnson Lake (8 July 2010)**



**Photograph 04. Outflow from Varnson Lake into Squall Lake (background) (5 Sept 2007)**



**Photograph 05. Southeast end of Squall Lake (5 Sept 2007)**



**Photograph 06. Beach at south shore of Squall Lake looking East (5 Sept 2007)**



**Photograph 07. Under canopy on south shore of Squall Lake (5 Sept 2007)**



**Photograph 08. Snow Creek between Squall Lake and Snow Lake (5 Sept 2007)**



**Photograph 09. Outflow of Snow Creek into Snow Lake looking south southeast (5 Sept 2007)**



**Photograph 10. Snow Lake looking East (5 Sept 2007)**



**Photograph 11. Power line crossing to Chisel Lake across Snow Lake, looking North (5 Sept 2007)**



**Photograph 12. Tern Lake looking east, power line in background (5 Sept 2007)**



**Photograph 13. Drainage channel to Tern Lake, PR 305 in background, looking south southeast (5 Sept 2007)**



**Photograph 14. Aerial view of Tern Lake (P7080029) (8 July 2010)**



**Photograph 15. Tern Creek along PR 395 looking northwest (6 Sept 2007)**



**Photograph 16. Sampling location in Tern Creek (8 July 2010)**



**Photograph 17. Sampling location in Tern Ditch (8 July 2010)**



**Photograph 18. Tern Ditch culvert in old rail bed north of Ghost Lake, looking north (6 Sept 2007)**



**Photograph 19. Tern Ditch crossing looking south (6 July 2010)**



**Photograph 20. Rocky habitat in Tern Ditch Pond (8 July 2010)**



**Photograph 21. Shoreline habitat in Tern Ditch Pond (8 July 2010)**



**Photograph 22. Cook Lake looking south (5 Sept 2007)**



**Photograph 23. Cook Lake looking south (5 Sept 2007)**



**Photograph 24. Two drill casings in Cook Lake (9 Sept 2008)**




Photograph 25. C01- Four season cabin and dock on peninsula of Cook Lake (9 Sept 2008)



Photograph 26. 41 cm Walleye caught on east shore of Cook Lake (9 Sept 2008)



**Photograph 27. Pair of bald eagles in south arm of Cook Lake. (One adult, one juvenile) (10 Sept 2008)**



**Photograph 28. Cook Lake: red staining and oxidized weathering on bedrock face (9 Sept 2008)**



**Photograph 29. Lalor Lake temporary water supply (8 July 2010)**



**Photograph 30. Aerial view of Lalor Lake (8 July 2010)**