UNIT NUMBER:

SORINE AREA OF SERVICE: HUDSON BAY & JAMES BAY

PHYSICAL DESCRIPTION:

Barque.

Construction:

Designer and builder:

Dimensions:

Draft:

Number of passengers: Number of crew: 13

Plans: Power: Registered: Speed: Tonnage:

HISTORY:

1910-1911 Returned to Carlton requiring extensive repairs. The crew refused to go to sea, so she was to winter at

Carlton with ten of the crew, the other three being brought to Moose Factory and sent to Cochrane by

canoe to cable the owners in Denmark (A.12/FT 288/1, fos. 3-15).

MASTERS:

Captain Anderson A.12/FT 288/1, fo. 3

BIBLIOGRAPHY:

 ${\bf PHOTOGRAPHS\ AND\ DOCUMENTARY\ ART:}$

1987/363-S-37 and others

REFERENCES:A.12/FT 288/1 fos. 3-15 London Inward Correspondence, 1910-1911

(824)

Search File: "Ships - Sorine"

Filename: Sorine 1983/AM (Revised April 1988/JHB:wg); April/99/mhd