


PHOTOGRAPH #1: FACING NORTH, SHOWING THE EXISTING SITE CONDITIONS NEAR THE WEST PROPERTY BOUNDARY.



PHOTOGRAPH #4:FACING SOUTHWEST SHOWING THE EXISTING SITE CONDITIONS ALONG WEST PROPERLY BOUNDARY



P:12020\130(True North Ag Development)\01(Nursery Hog Barn Manure Storage Lagoon)\Figures\Figure 8- Photograph 1 to 6.dwg


LEGEND



PHOTOGRAPH #2: FACING NORTH, SHOWING THE EXISTING SITE CONDITIONS ALONG MID-POINT OF THE PROPERTY.



PHOTOGRAPH #5: FACING NORTH, SHOWING AERIAL VIEW OF THE PROPOSED DEVELOPMENT AREA.





PHOTOGRAPH #3: FACING NORTH, SHOWING THE EXISTING SITE CONDITIONS ALONG EAST PROPERTY BOUNDARY.



PHOTOGRAPH #6: FACING NORTHEAST, SHOWING THE EXISTING SITE CONDITIONS AND TREE LINE ALONG THE NORTH AND EAST PROPERTY BOUNDARY.

	No.	DATE	18	ISSUE /REVISION		
			+-			
	0	0 APR. 2021		construction		
ENG-TECH CONSULTING LIMITED Phone: (1)					Turenne Street Winnipeg, MB R2J 3W8 (204) 233-1694 (204) 235-1579	
	ENG. STAMP					
-	The state of the s	C.D. HRYHORUK		MA Certificate of A	ulting Limited	
	CLIENT: TRUE NORTH AG DEVELOPMENT INC PROJECT: NURSERY HOG BARN AND EMS PROJECT SE-5-26-12W1 EDDYSTONE, MANITOBA DWG DESCRIPTION: PHOTOGRAPH 1-6 SCALE: N/A					
	DRAWN BY: DATE: TDR APRIL 2021					
FILE No.: CLIENT DWG/FIG. No.: 20-130-01						
	ENG-TECH DWG/FIG. No.: 13 OF 13				NO.:	