

# APPENDIX

## **E** PHOTOGRAPHS





*Photo 1. Start of pipeline facing south towards the well site at section C102.*



*Photo 2. Start of pipeline facing northwest at section C102.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 3. Start of pipeline facing west at section C102.*



*Photo 4. Cattle to the east at section C102.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 5. Infrastructure that could provide wildlife habitat at section C102 facing east.*



*Photo 6. Potentially some natural vegetation at section C102, facing northeast.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 7. Oak and aspen trees at section C102, facing west.*



*Photo 8. Tame pasture at section C102, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 9. Cattails from a wetland at section C102, facing northeast.*



*Photo 10. Forested habitat with snags at section C102/C103, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 11. Forested habitat at section C103, facing north.*



*Photo 12. Game trail in forest at section C103, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 13. Natural vegetation in previous drain at section C103, facing east.*



*Photo 14. Previous drain at section C103, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 15. Natural forested vegetation at section C103, facing west within the southern section of interest.*



*Photo 16. Section C103, facing east within the southern section of interest.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 17. Tame pasture at section C103/104, facing northeast.*



*Photo 18. Tame pasture at section C103/104, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 19. Crop field at section C104, facing north.*



*Photo 20. Wetland area/previous drain at section C104, facing north.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 21. Tame pasture at section C104, facing north.*



*Photo 22. Tame pasture and snags at section C104, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 23. Clump of forest at section C104, facing south.*



*Photo 24. Stick nest near a residence at section C104, facing south.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 25. Residence with snags and mixed forest at section C104, facing south.*



*Photo 26. Wetland area at section C104, facing north.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 27. Natural area between two crop fields at section C104, facing east.*



*Photo 28. Forested habitat at section C105, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 29. Crop field at section C105, facing west.*



*Photo 30. Forested habitat at section C105, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 31. Tame pasture at section C105, facing west.*



*Photo 32. Forest habitat and infrastructure at section C105, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 33. Forested habitat at section C105, facing east.*



*Photo 34. Tame pasture at section C105, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 35. Crop field and hydro line at section C105, facing northeast.*



*Photo 36. Tame pasture at section C105, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 37. Wetland at section C105, facing east.*



*Photo 38. Wetland at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 39. Tame pasture at section C106, facing west.*



*Photo 40. Ungulate trail at section C106, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 41. Tame pasture at section C106, facing west.*



*Photo 42. Crop field with shrubs at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 43. Game trail where the deer was observed at section C106, facing west.*



*Photo 44. Wetland at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 45. Potential bank swallow habitat at section C106, facing east.*



*Photo 46. Wetland habitat at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 47. Tame pasture at section C106, facing west.*



*Photo 48. Hole in tree likely from woodpecker at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 49. Wetland or drain habitat by the highway at section C106, facing east.*



*Photo 50. Drain habitat at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 51. Forested habitat at section C106, facing west.*



*Photo 52. Wetland habitat at section C106, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 53. Building at section C107, facing west.*



*Photo 54. Forested habitat near residence at section C107, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 55. Tame pasture or crop at section C108, facing west.*



*Photo 56. Crop at section C108, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 57. Game trails, forest, and tame pasture at section C108, facing west.*



*Photo 58. Snow covered road with natural ditches at section C109, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 59. Forested habitat where the road was no longer accessible at section C110, facing west.*



*Photo 60. Forested habitat and field where deer were observed at section C110, facing east.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 61. Snow covered road at section C111, facing south.*



*Photo 62. Crop at section C111, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 63. Crop at section C111, facing east.*



*Photo 64. Shrubby habitat at section C111, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 65. Shelterbelt and building at section C112, facing east.*



*Photo 66. Forested habitat and shelterbelt at section C112, facing north.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 67. Tame pasture at section C112, facing west.*



*Photo 68. Forested habitat and drain at section C112, facing northeast.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba



*Photo 69. Forested habitat with snags and drain at section C112, facing west.*



Date Taken: December 21,  
2022

Taken by: Alyssa Reimer

Project No.: 221-10243-00

Client: Monarch Hutterite  
Colony

Location: Birtle, Manitoba